

COLUMBIA CLUB ROOFTOP VENUE


# **ANNUAL MEETING PROGRESS REPORT**



# **AGENDA**

- PLATINUM SOCIETY PROJECTS TIMELINE
- ROOFTOP PURPOSE & VISION
- DESIGN PROGRESSION
- PLANS & RENDERINGS
- COST PROJECTIONS
- QUESTIONS & NEXT STEPS

# **PLATINUM SOCIETY PROJECTS TIMELINE**



APRIL 13, 2023 / © 2023 RATIO ARCHITECTS, LLC AND ITS AFFILIATES


# **VISION & PURPOSE**

A strategic initiative of the Columbia Club is to embrace the passion of our current and future members through offering enriched personal experiences.

We will build on a new dynamic to ensure our Club remains relevant, viable, and vibrant for future Columbian generations.

Through the Rooftop Venue project, we can **enhance the member experience** & attract new members with an intimate atmosphere, comfortable dining environment, & a multi-season outdoor space that creates an **experience unlike anything else** in Indianapolis.


# **NEARBY DOWNTOWN ROOFTOP PROJECTS**




# **PREVIOUS THINKING**

- Open roof deck only
- Two exit stairs
- One dumbwaiter lift (no elevators)
- No interior bar/dining
- No kitchen

- No restrooms
- Railing at the roof edge
- Original construction costs never verified
- Original \$2M donation withdrawn
- COVID Pandemic





2022 CONCEPTUAL DIAGRAM

PRE-2022 CONCEPTUAL DIAGRAM


























APRIL 13, 2023 / © 2023 RATIO ARCHITECTS, LLC AND ITS AFFILIATES

TOTAL GSF: 5,390 SF

**OUTDOOR FRONT ROOFDECK:** 

1,775 SF

**OUTDOOR CIGAR LAZE:** 

325 SF

INTERIOR:

3,290 SF TOTAL

- 20' CANTILEVER OVER BALLROOM
- INDOOR CIGAR LAZE W/ PRIVATE PATIO
- SINGLE ELEVATOR UP TO LOBBY



TOTAL GSF: 3,750 SF

**OUTDOOR FRONT ROOFDECK:** 

1,535 SF


**OUTDOOR CIGAR LAZE:** 

350 SF

**INTERIOR:** 

1,865 SF TOTAL

- 7' CANTILEVER OVER BALLROOM
- SINGLE ELEVATOR UP TO LOBBY
- 1 SINGLE-USE RESTROOM



# DESIGN OPTIONS UNDER CONSIDERATION

I. ROOF REPLACEMENT

+

II. OUTDOOR ROOF DECKS

+

III. INDOOR AREA

=

**OUR WISHLIST** 



APRIL 10, 2023 / © 2023 RATIO ARCHITECTS, LLC AND ITS AFFILIATES

**TOTAL GSF:** 

3,300 SF, SEATS: 115

**OUTDOOR FRONT ROOFDECK:** 

1,500 SF, SEATS: 55


**OUTDOOR CIGAR LAZE:** 

200 SF, SEATS: 10

**INTERIOR:** 


1,600 SF TOTAL, SEATS: 50

- SATELLITTE KITCHEN + FULL BAR
- 2 SINGLE-USE RESTROOMS
- NO CANTILEVER OVER BALLROOM
- 2 EXIT STAIRS
- 2 PASSENGER ELEVATORS UP TO LOBBY
- 1 SERVICE ELEVATOR WITH SERVICE PATH
- RELOCATE HVAC UNIT TO ALT ROOF AREA
- LOUNGE FURNITURE
- TABLES WITH CHAIRS
- 50% OUTDOOR SEATS UNDER COVER
- FIRE PIT AREA
- WIFI & USB CHARGING
- ROOF REPLACEMENT



APRIL 10, 2023 / © 2023 RATIO ARCHITECTS, LLC AND ITS AFFILIATES

# **WISHLIST OPTION** PLAN PERSPECTIVE



# WISHLIST OPTION ROOFTOP AERIAL




APRIL 10, 2023 / © 2023 RATIO ARCHITECTS, LLC AND ITS AFFILIATES

COlumbia Club - Indianapolis Rooftop Schematic Design

# WISHLIST OPTION EXTERIOR PERSPECTIVE



APRIL 10, 2023 / © 2023 RATIO ARCHITECTS, LLC AND ITS AFFILIATES





APRIL 10, 2023 / © 2023 RATIO ARCHITECTS, LLC AND ITS AFFILIATES

COlumbia Club - Indianapolis Rooftop Schematic Design



TOTAL GSF:

2,100 SF, SEATS: 55


#### **OUTDOOR FRONT ROOFDECK:**

1,500 SF, SEATS: 55

INTERIOR:

600 SF TOTAL, SEATS: 0 (STAIR/ SERVICE)

- FOOD & BEVERAGE SERVICE AT TIMED EVENTS FROM 3<sup>RD</sup> FLOOR KITCHEN AND/OR CATERING KITCHEN AT 10<sup>TH</sup> FLOOR
- RESTROOMS AT 10<sup>TH</sup> FLOOR
- NO CANTILEVER OVER BALLROOM
- 2 EXIT STAIRS
- 1 LIFT FROM 10<sup>TH</sup> FLOOR
- 1 SERVICE ELEVATOR WITH SERVICE PATH
- RELOCATE HVAC UNIT TO ALT ROOF AREA
- LOUNGE FURNITURE
- TABLES WITH CHAIRS
- LARGE UMBRELLAS FOR SHADE
- FIRE PIT AREA
- WIFI & USB CHARGING
- ROOF REPLACEMENT



APRIL 10, 2023 / © 2023 RATIO ARCHITECTS, LLC AND ITS AFFILIATES

# **OPTION 2** ROOFTOP AERIAL



APRIL 10, 2023 / © 2023 RATIO ARCHITECTS, LLC AND ITS AFFILIATES

COlumbia Club - Indianapolis Rooftop Schematic Design

# **OPTION 2** EXTERIOR PERSPECTIVE



# ORDER OF MAGNITUDE ESTIMATES

Phase I ROOF REPLACEMENT ONLY	Total Project <u>Estimate</u> \$1,000,000	Construction <u>Duration</u> 2-3 months
Phase II ACCESSIBLE OUTDOOR ROOF DECK	\$4,920,000	6-9 months
Phase I and II COMBINED	\$5,740,000*	
Phase III INDOOR ROOFTOP SPACE + CIGAR LAZE + PASSENGER ELEVATORS	\$6,200,000	6-9 months
Phase I, II, and III CONSTRUCTED SIMULTANEOUSLY*	* \$9,600,000*	11-12 months
Phase I, II, and III CONSTRUCTED SEPARATELY	\$12,120,000	

### **KEY COST CONSIDERATIONS**

- Includes economy of scale savings\*
- Each estimate includes the following:
  - 20% design & construction contingency
  - Owner soft costs (furniture, equipment WIFI, etc, as applicable)
  - Costs incurred to date related to rooftop venue project
- Estimates exclude cell tower & monument circle lighting work as options continue to be explored.
- If all work is constructed simultaneously\*\*,
  - 20% savings realized
  - **30%** of costs relate to creating roof access (stair, elevator, etc)
  - 10% of costs relate to complexities of working on Monument Circle, 11 floors up on a roof
- Construction cost estimates developed by Brandt Construction.
- Soft cost estimates developed by J.S. Held

## **PHASE II**



### **PHASE II SCOPE SUMMARY**

- Develop 1,500 SF outdoor roof deck with seating for 55 people at lounge furniture and tables/chairs with umbrellas shade
- WIFI and USB charging
- Incorporate plantings and fire pits to extend seasonal use
- Create small vertical lift from 10<sup>th</sup> floor (not a full elevator)

- Utilize 10<sup>th</sup> floor restrooms
- Extend 2 exit stairs to roof
- Extend service elevator for timed event food & beverage and a roof path for carts
- Provide code compliant rails, etc
- Relocate HVAC equipment for the new deck

## **PHASE III**



### **PHASE III SCOPE SUMMARY**

- Develop 1,200 SF indoor roof deck venue with indoor bar, satellite kitchen, restrooms, and tables/chairs
- Dedicated outdoor cigar laze
- Overhead shade covering for outdoor seating

- 50 indoor seats
- 10 cigar laze seats
- Extend 2 guest elevators to the roof
- Relocate additional HVAC equipment

